

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO. : 7,059,152

APPLICATION NO.: 10/701,702

ISSUE DATE : June13, 2006

INVENTOR(S) : John Douglas OKEY, Brian Morice DAVIES

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 5, line 52, replace "moie" with --mole--.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Philip H. Von Neida, The BOC Group, Inc., Intellectual Property Dept.
575 Mountain Avenue, Murray Hill, NJ 07974

Attorney Docket: M02B131

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicants: John Douglas OKEY, Brian Morice DAVIES
Patent No.: 7,059,152 Issued: June 13, 2006
Serial No.: 10/701,702 Filed: November 5, 2003
Attorney Docket: M02B131 Confirmation No.: 7081
Title: Nitrogen Rejection Method and Apparatus

Commissioner for Patents
ATTN: Certificate of Correction Branch
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

A printing error has been discovered in the above-identified United States patent. A completed form for a Certificate of Correction which lists and corrects this error is enclosed herewith.

Inasmuch as the applicants submit that this error was introduced through no fault of the applicants, the applicants believe that no fee is due for the Certificate of Correction.

In the event a fee is due, kindly charge that fee to deposit account number 02-2865.

Respectfully submitted,

/Philip H. Von Neida/

Correspondence Information
Customer Number: 20411
Phone 908-771-6402
Fax: 908-771-6159

Philip H. Von Neida
Registration No. 34,942
Attorney for Applicants
Date: July 13, 2006